

T-10 COMPLETE TRANSMISSION RATIOS

	1ST	2ND	3RD	4TH
W	2.64	1.75	1.33	1*1
X	2.64	1.61	1.23	1*1
S	2.43	1.61	1.23	1*1
Q	2.43	1.46	1.18	1*1
CC	2.88	1.91	1.33	1*1
Z	3.42	2.28	1.46	1*1
T	2.43	1.61	1.03	1*1
Y	2.88	1.75	1.33	1*1

T-10 TOOTH COUNT RATIO CHART

RATIO	INPUT	CLUSTER	1ST	2ND	3RD
		I-3RD-2ND-1ST			
W	20	28-23-20-18	34	25	22
X	20	28-24-21-18	34	24	21
S	21	27-23-20-18	34	25	22
Q	21	27-28-21-18	34	24	26
CC	19	29-24-20-18	34	25	21
Z	17	31-25-20-16	30	25	20
T	21	27-25-20-16	30	25	20
Y	19	29-24-21-18	34	24	21
EE(2.88)	19	29-25-21-18	34	24	20